



# HILLTOWN TOWNSHIP

13 West Creamery Road

P.O. Box 260

Hilltown, PA 18927

(215) 453-6000

June 29, 2005

To the residents of Longleaf II,

This is the fourth letter in a series of updates to the concerns voiced at the May 23, 2005 meeting of the Hilltown Township Board of Supervisors. As a reminder, the concerns raised were related to the fire sprinkler systems in the second phase of the Longleaf development.

The Township is in the process of scheduling inspections of the sprinkler systems. We are calling all of those who have provided us with a phone number to set up an appointment. This will be a process that will take some time. Please be patient as we work our way through the list.

If you have not provided us with a phone number, please send an email with your name, address, and phone number to [djenkins@hilltown.org](mailto:djenkins@hilltown.org) and we will add you to the list. Although this entire process will be optional on your part, we strongly recommend that you agree, as it will allow for more complete and accurate data to evaluate.

Should you have any further questions, please do not hesitate to contact the Township so that we may include it in a future update.

Again, we encourage you to send an email to [djenkins@hilltown.org](mailto:djenkins@hilltown.org) to receive these updates by email. Please be sure to identify your street address, so that we may reduce the duplicate mailings.

Respectfully,

Daniel A. Jenkins, MCP  
Fire Marshal

David W. Taylor, CBO  
Building Code Official

## Longleaf Phase II Fire Sprinkler Update #4

### Heritage Activities:

“At this time there is nothing definitive on why the pipes are cracking. Our engineer and the Noveon and Harvel people have had multiple conference calls to discuss findings and testing methodology. Additional calls are planned for this week. I was instructed to take samples of fluid and piping from a home where the work was completed by Qualified. I did so at Mr. Bogan’s house this morning.

Larry Wargo” – Via email 6/27/05

### Township Activities:

- Phone calls to schedule inspections have begun.
- Inspections are expected to begin the first week of July.